# The following site is being submitted for inclusion into the GIS registry:

This is a:	New Submittal
BRRTS ID (no dashes):	0368212795
Comm # (no dashes):	53007130640
County:	Waukesha
Region:	Commerce
Site name:	Snyder Property
Street Address:	5140 N 126th St
City:	Butler
Closure Date	2001-05-17
Closure Conditions:	met
Offsite contamination?	No
Right-of-way contamination?	No
Contaminated media:	Groundwater
GPS Coordinates (meters in the	e WTM91 projection)
Easting (X):	677184.191242134
Northing (Y):	294916.325261729
Submitted by:	Cheryl Nelson
	· · · · · · · · · · · · · · · · · · ·

### Checklist

$\bowtie$	Final Closure Letter
$\boxtimes$	Copy of recorded deed Instrument for any property with GW >NR140 ES
$\boxtimes$	General Location Map
$\boxtimes$	Detailed Location Map showing property boundaries, buildings, etc for properties with GW >NR140 ES
	Latest Map(s) showing extent or outline of current GW plume
	GW flow direction
$\boxtimes$	MW(s) and/or potable wells
$\boxtimes$	Latest Table of GW results





Scott McCallum, Governor Brenda J. Blanchard, Secretary

May 17, 2001

Mr. Jerry and Mr. Thomas Snyder 5140 North 126<sup>th</sup> Street Butler, WI 53007-1306

RE: Final Case Closure Snyder Property, 5140 North 126<sup>th</sup> St., Butler, WI Commerce #: 53007-1306-40A WDNR BRRTS #: 03-68-212795

Dear Misters Snyder:

On May 2, 2001, the Department received all of the conditions required for closure (deed notification, monitoring well abandonment, tank disposal, etc.) from your consultant, A.E.S. Consultants, LTD. The Department's database has been updated to reflect the closed status of your site.

If you have any questions feel free to contact me at (414) 220-5375.

Sincerely,

Gregory S. Michael
Hydrogeologist
Department of Commerce
PECFA Site Review Section

Cc:

electronic storage

AFS

Thomas Snyder, 3397 Mount Lane, Hubertus, WI 53033

## MAR 20 01 0 0 1 3 7 \$

# NOTICE OF CONTAMINATION TO

PROPERTY

ed)

1-262 375-8356

From Tom Snyder

F-262 628-0540

STATE OF WISCONSIN

COUNTY OF Workesha

53

2634629

REGISTER'S OFFICE WAUKESHA COUNTY. WI RECURDED ON

03-20-2001 11:14 AM

MICHAEL J. HASSLINGER REGISTER OF DEEDS

REC. FEE-CO: 4.00 REC. FEE-ST: 2.1 [RAN. FEE: TRAN. FEE-STATE: 2. 00 PAGES:

Recording Area

Name and Return Address

THOMAS E SNYCLER 3397 MOUNT LANG

Hubertus was Islan

Parcel Identification Number (PIN)

THOMAS E Sound crais the owner of the above-described property. Section 1.

One or more petroleum discharges have occurred at this property. Petroleum contaminated Section 2. groundwater above NR 140 enforcement standards and petroleum contaminated soil above NR 720 residual contaminant levels of the Wisconsin Administrative Code exist(s) on this property.

The owner hereby declares that all of the property described above is held and shall be held, Section 3. conveyed or encumbered, leased, rented, used, occupied and improved subject to the following limitations and/or restrictions:

Residual petroleum contaminated soil remains on this site. According to the Case Summary and Close Out Request report filed by A.E.S. Consultants, Ltd., dated October 10, 2000, the residual soils are located on-site to the west of the driveway located on the north side of the Snyder Grinding building, as well as beneath the building. If contaminated soil is excavated in the future, it will have to be sampled and analyzed and the treatment or disposal of the soil in accordance with all applicable laws as a solid or hazardous waste may be necessary (File references: PECFA Claim # 53007-1306-40 and BRRTS # 03-68-212795).

Residual groundwater contamination is also present on-site as identified in monitoring well MW-1 located near the former underground storage tank basin, which was also located to the north of the Snyder Grinding Building. Natural attenuation is the approved remedial alternative for this site. Anyone who proposes to construct or reconstruct a well on this property is required to contact the Department of Natural Resources' Bureau of Drinking Water and Groundwater, or its successor agency, to determine what specific prohibitions or requirements are applicable, prior to constructing or reconstructing a well on this property. No well may be constructed or be constructed on this property unless applicable requirements are met.

Any person who is or becomes owner of the property described above may request that the Wisconsin Department of Commerce, or its successor, issue a determination that the restrictions set forth in this covenant are no longer required. That property owner shall provide any and all necessary information to the Department in order for the Department to be able to make a determination. Upon receipt of such a request, the Department shall determine whether or not the restrictions contained herein can be extinguished. Conditions under which a restriction may be extinguished will be determined in accordance with the site specific standards, rules and laws for this property. If the Department determines that the restrictions can be extinguished, an affidavit, with a copy of the Department's written determination, may be recorded to give notice that this restriction, or portions of this restriction are no longer binding. Any restriction placed upon this property shall not be extinguished without the Department's written determination.


IN WITNESS WHEREOF, the owner of the property has executed this document, this <u>lo</u> day of March, 2001.
[When appropriate use the following clause]:
By signing this document, [he/she] acknowledges that [he/she] is duly authorized to sign this document on behalf of
Signature: Tamas E Suyla
Printed Name: THomas E Sayder
Title:
Subscribed and sworn to before me this 20" day of MARCH, 2001.  Schruck Remu deputy Notary Public, State of Wisconsu  My commission 12 - 31-02  706.07 (3)

This document was drafted by the Wisconsin Department of Commerce.

CHELLY CHER

### **EXHIBIT A**

Lots 15 and 16, Block 7 in Village of Butler, formerly New Butler, being a part of the Southeast 1/4 of Section 36, Town of Menomonee, and Northeast 1/4, Town of Brookfield, Waukesha County, Wisconsin, according to the recorded plat thereof.






				TABLE 2	2 5					
		• •	ANALYTICAL RESULTS - GROUNDWATER	RESULTS	S - GROUN	<b>DWATER</b>				
		SNY	SNYDER GRINDING SITE - BUTLER, WISCONSIN	ING SITE	BUTLER,	WISCONS	Z			
	NR 140	40					Samples			
	Remedial Action Limits	dial imits	NR 746 Standards	MW-1A	MW-1A Dup	MW-1B	MW-1B Dup	Trip Blank	MW-1	Trip Blank
Well / Boring	ES	PAL		MW-1	MW-1	MW-1	MW-1	1	MW-1	1
Dorth (feet)				5-15'	5-15'	5-15'	5-15	1	5-15'	1
Date Sampled				3/3/00	3/3/00	00/5/9	00/2/9	00/2/9	9/18/00	9/18/00
ANAI YTE					1			1		-
Total Lead (110/1)	15	1.5								
				<1.0						
Renzene	5	0.5	1,500	1.03	1.1	32	32	<0.39	42	<0.39
1 2-Dichloroethane	5	0.5	1.500	<0.36	1					
Ethylbonzono	2007	140	7.400	<0.34	<0.34	15	14	<0.4	25	<0.4
Methyl-fert-butyl-ether	99	12		1.8	1.4	<0.47	<0.47	<0.47	<0.47	<0.47
Naphthalene	40	8		<0.88		-		-	-	
Toluene	1,000	200	20,000	<0.35	<0.35	2.8	2.8	<0.37	3.40	<0.37
1 2 4-Trimethylbenzene		3		<0.35	<0.35	15	15	<0.4 4.0	28	<0.4
1.3.5-Trimethylbenzene	480	96		<0.64	<0.64	4.6	4.7	<0.63	7.6	<0.63
Total Xvlenes	10.000	1,000	7,800	>0.66	<1.0	39.2	39.3	<1.4	55	<1.4
Total VOCs / PVOCs				2.8	2.5	109	108	0	161	0
Ida voor i voor										

Bold type indicates concentrations exceeding the PAL. Shaded areas indicate concentrations above the ES.

Bold, red type indicates concentrations exceeding NR 746 groundwater standards for low-permeability materials.

Only VOCs detected or having applicable cleanup standards are listed. For a complete list of the compounds analyzed and laboratory detection limits, see Appendix E. ---- = not analyzed

 $<sup>^2</sup>$  Analyte detected between LOD and LOQ  $\,$ see Appendix E.